



NOTICE OF SUSPENSION OF SUPPLEMENTAL TYPE CERTIFICATE SVA521

Notice under subregulation 21.118 (4) of the *Civil Aviation Safety Regulations 1998*

For subregulation 21.118 (4) of the *Civil Aviation Safety Regulations 1998 (CASR 1998)*, notice of the suspension of Supplemental Type Certificate No. SVA521 (the *certificate*) is given.

The certificate is suspended, in accordance with regulation 11.130 of CASR 1998, on the grounds that the holder of the certificate, Rebel Ag Pty Ltd, has applied to CASA for the certificate to be suspended.

Under subregulation 21.118 (5) of CASR 1998, a suspension of a supplemental type certificate takes effect on the day after the notice of the suspension is published in the *Gazette*.

In accordance with paragraph 11.130 (2) (a) of CASR 1998, the suspension ceases to have effect when the Australian Transport Safety Bureau publishes a final report under section 25 of the *Transport Safety Investigation Act 2003* in relation to the accident on 24 October 2013 involving the PZL Mielec M18A Dromader aircraft with the set of markings VH-TZJ.

[Signed Peter Nikolic]

Peter Nikolic
Manager Initial Airworthiness
Airworthiness and Engineering Standards Branch
Standards Division
Civil Aviation Safety Authority

19 August 2015