Airworthiness Directives 2004

- I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:
 - (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
 - (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.

David Villiers

Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

Cessna T303 Series Aeroplanes

AD Name	AD Number
Fuel Hose Clamping - Improvement	AD/CESSNA 303/1
Flight Into Icing Conditions	AD/CESSNA 303/2 Amdt 1
Exhaust Gas and Fuel Leakage in Engine Compartment	AD/CESSNA 303/3
Prohibition of Flight in Known Icing Conditions	AD/CESSNA 303/4 Amdt 2
Turbocharger and Exhaust Mount	AD/CESSNA 303/5 Amdt 1
Seat Adjustment Mechanism	AD/CESSNA 303/6 Amdt 1
NLG Actuator Attach Fitting	AD/CESSNA 303/7 Amdt 1
Slick Pressurized Magnetos	AD/CESSNA 303/8
Slick Pressurized Magnetos - Flight Manual	AD/CESSNA 303/9 Amdt 1
Auxiliary Fuel Pump Wiring Modification	AD/CESSNA 303/10
Inlet Fuel Valve Assembly	AD/CESSNA 303/11 Amdt
Aircraft Flight Manual, Flight into Icing Conditions	AD/CESSNA 303/12 Amdt