

Airworthiness Directives 2004

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.



David Villiers
Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

DHA-3 (drover) Series Aeroplanes

AD Name	AD Number
Electrical Installation - Modification	AD/DHA-3/1
Wing Assembly - Modification	AD/DHA-3/2
Wing Engine Mount Cross Brace Tube - Modification	AD/DHA-3/3
Fuel Tank Vent - Modification	AD/DHA-3/4
Windscreen Wiper - Modification	AD/DHA-3/5
Fuel Filter - Modification	AD/DHA-3/6
Horizontal Tail Plane Attachments - Modification	AD/DHA-3/7
Electrical Cable Insulation - Modification	AD/DHA-3/8
Battery Master Switch Insulation - Modification	AD/DHA-3/9
Hand Brake Installation - Modification	AD/DHA-3/10
CANCELLED	AD/DHA-3/11
CANCELLED	AD/DHA-3/12
Horizontal Tailplane Attachments - Inspection	AD/DHA-3/13
Fairey-Reed Propellers - Spinner Removal	AD/DHA-3/14
Rear Fuselage - Elevator Quadrant Installation - Modification	AD/DHA-3/15
Undercarriage Bolts P/N U3-129 - Inspection	AD/DHA-3/16 Amdt 1
Fuselage at Wing Rear Pickups - Modification	AD/DHA-3/17
Fuselage - Cross Beam and Attachment Brackets at Firewall - Modification	AD/DHA-3/18
Fuselage - Installation of Strengthened Support Brackets - Lower Centre Engine Mounts	AD/DHA-3/19
Wing Rib No. 5 - Inspection	AD/DHA-3/20
Corrosion of Wing and Centre Section Spar Booms - Inspection	AD/DHA-3/21
Flap Link Attachment Bracket (Outer) - Inspection	AD/DHA-3/22
Flap Inner Link Attachment Brackets - Inspection	AD/DHA-3/23
Tailplane Spar and Elevator Hinge Stiffener Bracket - Inspection	AD/DHA-3/24 Amdt 1
Centre Section and Wing Spar - Life Limitations	AD/DHA-3/25 Amdt 2
Front Seat Restraint Installation - Modification	AD/DHA-3/26
Wing to Fuselage Attachments - Inspection	AD/DHA-3/27
Centre Section Main Spar Upper Boom Attach Fitting - Inspection	AD/DHA-3/28