

Airworthiness Directives 2004

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.



David Villiers
Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

Eurocopter BO 105 Series Helicopters

AD Name	AD Number
Tandem Hydraulic Units - Water in Servo Valve	AD/BO 105/1
Tail Rotor Blade Grips	AD/BO 105/2 Amdt 1
Tail Rotor Gearbox Attachment	AD/BO 105/3
Dual Flight Controls	AD/BO 105/4
Tandem Hydraulic Units - Piston Rods	AD/BO 105/5
Fuel Filter Drain Valve	AD/BO 105/6
Fatigue Life Limitations	AD/BO 105/7 Amdt 1
Tail Boom Skin	AD/BO 105/8
Main Rotor Blade Grip Bolts	AD/BO 105/9
Swashplate	AD/BO 105/10
Tail Rotor Transmission	AD/BO 105/11 Amdt 1
Rotating Control Rod End Bearings	AD/BO 105/12
Load Hook System	AD/BO 105/13
Dual Hydraulic System Switch Over	AD/BO 105/14
Transmission Flange Shimming	AD/BO 105/15