

## **Airworthiness Directives 2004**

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.



David Villiers  
Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

# Schedule 1      Revocation and Remaking of Airworthiness Directives

## Airconditioning Equipment

<b>AD Name</b>	<b>AD Number</b>
Godfrey Cabin Supercharger Type 15 - Banjo Fitting - Modification	AD/AIRCON/1
Godfrey Cabin Supercharger Type 15 - Modification	AD/AIRCON/2
Godfrey Cabin Supercharger Type 15 - Rotor Balance - Inspection	AD/AIRCON/3
Cabin Heater - Cessna Combustion Type - Inspection and Reconditioning -	AD/AIRCON/4
Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection	AD/AIRCON/5
Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection	AD/AIRCON/6
Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection	AD/AIRCON/7
Cabin Heater - Midland Ross Corp. (Janitrol) - Combustion Type - Inspection	AD/AIRCON/8 Amdt 2
Combustion Type Cabin Heaters	AD/AIRCON/9 Amdt 7
Janitrol Cabin Heaters	AD/AIRCON/10
ABG Semca Cold Air Unit - Compressor Wheel and Scroll	AD/AIRCON/11
Kelly Aerospace Power Systems - Cabin Combustion Heaters	AD/AIRCON/12 Amdt 2
Janro Cabin Combustion Heaters	AD/AIRCON/13