Airworthiness Directives 2004

- I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:
 - (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
 - (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.

David Villiers

Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AD Name	AD Number
Never Exceed Speed Reduction	AD/BELL 407/1 Amdt 5
Warning Horns	AD/BELL 407/2
Thomas Coupling Pack - Cracked Discs - Inspection - CANCELLED	AD/BELL 407/3
Gearbox Barrier Tape Replacement - CANCELLED	AD/BELL 407/4
Hydraulic Relief Valve Replacement	AD/BELL 407/5
Engine to Transmission Driveshaft Replacement	AD/BELL 407/6
Tail Rotor Hanger Bearing Support Inspection	AD/BELL 407/7
Airworthiness Limitations - CANCELLED	AD/BELL 407/8
Tailboom Skin	AD/BELL 407/9 Amdt 2
Oil Cooler Blower Assembly - Bearing Change - CANCELLED	AD/BELL 407/10
Door Locking Mechanism	AD/BELL 407/11
Crew Seat Belt and Restraint Assembly	AD/BELL 407/12
Oil Cooler Driveshaft Bearings Check - CANCELLED	AD/BELL 407/13
Horizontal Stabiliser Slat	AD/BELL 407/14 Amdt 1
Engine to Transmission Shaft	AD/BELL 407/15 Amdt 1
Fuel Filler Cap Electrical Bonding	AD/BELL 407/16
Forward Bearing Hanger Support	AD/BELL 407/17
Fuel Line	AD/BELL 407/18
Tail Rotor Gearbox	AD/BELL 407/19
Tailboom Tail Rotor Gearbox Support Casting	AD/BELL 407/20 Amdt 1
Tail Rotor Drive Shaft Bearings - CANCELLED	AD/BELL 407/21 Amdt 2
Rescue Hoist	AD/BELL 407/22
Swashplate Drive Link	AD/BELL 407/23
Tail Rotor Gearbox	AD/BELL 407/24
Tail Rotor Drive Shaft Bearings	AD/BELL 407/25 Amdt 1
Landing Gear Cross Tubes	AD/BELL 407/26
Power Turbine RPM Steady State Operation Avoidance	AD/BELL 407/27
Freewheel Aft Bearing Cap	AD/BELL 407/28