

## **Airworthiness Directives 2004**

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.



David Villiers  
Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

# Schedule 1      Revocation and Remaking of Airworthiness Directives

## Cessna 336 Series Aeroplanes

<b>AD Name</b>	<b>AD Number</b>
Fuel Line - Replacement	AD/CESSNA 336/1
Cooling Fan - Inspection	AD/CESSNA 336/2
Plastic Control Wheel - Inspection	AD/CESSNA 336/3 Amdt 1
Open Wire rial Installation - Modification	AD/CESSNA 336/4
Fuel Quantity Gauge Cooling - Modification	AD/CESSNA 336/5
Front Seat Restraint Installations - Modification	AD/CESSNA 336/6
Rear Engine Idle Rpm - Adjustment and Placard Installation	AD/CESSNA 336/7
CANCELLED	AD/CESSNA 336/8 Amdt 1
Flap Actuator - Inspection and Modification	AD/CESSNA 336/9
Wing Front Carry Thru Spar Inspection and Modification	AD/CESSNA 336/10
Wing Front and Rear Spars - Inspection	AD/CESSNA 336/11 Amdt
Vented Fuel Caps - Installation	AD/CESSNA 336/12 Amdt
Seat Adjustment Mechanism	AD/CESSNA 336/13 Amdt
Upper Shoulder Harness Adjuster Spring	AD/CESSNA 336/14