Airworthiness Directives 2004

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.

David Villiers

Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

Hiller UH-12 Series Helicopters

| AD Name | AD Number |
|--|------------------------|
| Main Rotor Blade - Inspection | AD/HILLER 12/1 |
| Main Rotor Blade Spar - Inspection | AD/HILLER 12/2 |
| Tail Rotor Blade Assembly - Provision of Vent Hole | AD/HILLER 12/3 |
| Main Transmission - Inspection - CANCELLED | AD/HILLER 12/4 |
| Main Rotor Transmission Lube System - Modification - CANCELLED | AD/HILLER 12/5 Amdt 2 |
| Superseded by AD/HILLER 12/11 | AD/HILLER 12/6 |
| Wobble Plate Screws - Replacement - CANCELLED | AD/HILLER 12/7 Amdt 1 |
| Main Rotor Blade Fork | AD/HILLER 12/8 Amdt 3 |
| Horizontal Stabiliser Spar - Inspection | AD/HILLER 12/9 Amdt 1 |
| Main Rotor Blades - Inspection and Modification | AD/HILLER 12/10 |
| Tail Rotor Blades - Replacement - CANCELLED | AD/HILLER 12/11 |
| Main Rotor Blades - Inspection | AD/HILLER 12/12 Amdt 2 |
| Transmission Gear - Inspection | AD/HILLER 12/13 Amdt 2 |
| Main Rotor Blade Attach Pin Nut - Modification - CANCELLED | AD/HILLER 12/14 |
| Mercury Clutch Sideplates - Inspection - CANCELLED | AD/HILLER 12/15 |
| Cyclic Pitch Control Bracket Attach Bolts and Inserts - Inspection and | AD/HILLER 12/16 |
| Control Rotor Blade Assemblies | AD/HILLER 12/17 Amdt 4 |
| Retirement Life - Critical Components | AD/HILLER 12/18 Amdt 6 |
| Main Rotor Blades - Inspection | AD/HILLER 12/19 |
| Mercury Clutch - Operational Limitations - CANCELLED | AD/HILLER 12/20 |
| Main Rotor Drag Strut - Inspection - CANCELLED | AD/HILLER 12/21 |
| Main Rotor Hub | AD/HILLER 12/22 Amdt 3 |
| Main Rotor Blade, Anti Node Weight Retention - Inspection | AD/HILLER 12/23 Amdt 1 |
| Main Rotor Blade Doubler & Honeycomb Areas | AD/HILLER 12/24 Amdt 4 |
| Control Rod End Bearings - Inspection - CANCELLED | AD/HILLER 12/25 |
| Rotor Tachometer Generator - Replacement | AD/HILLER 12/26 |
| Outer Gimbal Forward Attach Fitting - Inspection | AD/HILLER 12/27 Amdt 2 |
| Main Rotor Blade Anti-Node Bar - Inspection | AD/HILLER 12/28 |
| Main Drive Torsion Coupling - Inspection and Replacement | AD/HILLER 12/29 Amdt 4 |

AD/HILLER 12/30 Amdt 2 Main Rotor Assembly Inspection of Lower Gearcase Oil Jets - Soloy Gas Turbine Conversion -AD/HILLER 12/31 Tail Rotor Control Balance Cable - Inspection - CANCELLED AD/HILLER 12/32 Tail Rotor Blade P/N 55073 - Inspection AD/HILLER 12/33 Main Transmission Oil Filter AD/HILLER 12/34 Amdt 1 Mercury Clutch Attach Bolts and Washers - Replacement - CANCELLED AD/HILLER 12/35 Amdt 1 Main Drive Torsion Coupling P/N 21047-15 - Inspection of Lower Plate AD/HILLER 12/36 Amdt 1 Soloy Conversion: Power Turbine Governor Control System - Modification AD/HILLER 12/37 Engine Mount Clevises AD/HILLER 12/38 Consolidation of Early Airworthiness Directives AD/HILLER 12/39 Main Rotor Assembly Drag Strut and T-T Bar Pin AD/HILLER 12/40 Amdt 2 Tail Rotor Blades AD/HILLER 12/41 Main Rotor Mast AD/HILLER 12/42 AD/HILLER 12/43 Control System Linkage